

CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-2214688-0
Report Reference E184430-20220408
Date 18-Apr-2022

Issued to: WEG DRIVES & CONTROLS - AUTOMACAO LTDA
AV PREFEITO WALDEMAR GRUBBA
3000
VILA LALAU JARAGUA DO SUL, SC 89256-900
Brazil

**This is to certify that
representative samples of**

NMMS - Power Conversion Equipment
See Addendum Page for Product Designation(s).

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 61800-5-1, 1st Ed., Issue Date: 2012-06-08, Revision
Date: 2021-02-11

Additional Information: See the UL Online Certifications Directory at
<https://iq.ulprospector.com> for additional information

This Certificate of Compliance does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-2214688-0
Report Reference E184430-20220408
Date 18-Apr-2022

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Model	Category Description
Power Conversion Equipment , Accessory communication modules, CFW32 followed by 0, 1, 2, 3, 4, 5, 6, 7, 8, or 9, followed by CUSB, CRS485, CRS232, CCAN, CBLT, CPDP, or CETH.	Power Conversion Equipment
Power Conversion Equipment , Accessory Flash Memory, MMF-uDRIVES	Power Conversion Equipment
Power Conversion Equipment , Accessory I/O modules, CFW32 followed by 0, 1, 2, 3, 4, 5, 6, 7, 8, or 9, followed by IOAR, IODR, IOAENC, IODF, IOADR, or IOADR-D, CFW32x-IOP.	Power Conversion Equipment
Power Conversion Equipment , Accessory Remote HMI, CFW32 followed by 0, 1, 2, 3, 4, 5, 6, 7, 8, or 9, followed by KHMIR.	Power Conversion Equipment
Power Conversion Equipment , CFW32, 0, 1, 2, 3, 4, 5, 6, 7, 8, or 9, followed by A, B or C, followed by 01P1, 01P6, 01P8, 02P6, 03P5, 04P2, 04P8, 06P0, 06P5, 07P3, 08P2, 10P0, 12P0, 15P0 or 15P2 followed by S, T, D or B, followed by 1, 2, 3 or 4, followed by NB or DB, followed by 20, may be followed by Hx, may be followed by Sx.	Power Conversion Equipment



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

