



## **Errata of the CFW-08 Manual**

## **Errata del Manual del CFW-08**

## **Errata do Manual do CFW-08**

In CFW-08 inverter model 16 A / 380-480 V with software version V5.24 or above, the adjust was fixed in 2.5 kHz.

En el modelo CFW-08 16 A / 380-480 V con versiones de software V5.24 o mayor, el ajuste del parámetro P297 es fijo en 2,5 kHz.

No modelo CFW-08 16 A / 380-480 V com versão de software V5.24 ou acima, o ajuste do parâmetro P297 é fixo em 2,5 kHz.