



Solar Pump Drive V2.02 Application Information

Equipment: CFW700

Firmware Version: V2.30 or higher

WLP Software Version: -

New Application Version: 2.02

Old Application Version: 2.01

Document Number (Application Manual): 10006763201 / 03

Functional deviations in the old application version

- 1) Low Voltage Stop based on Drive Undervoltage Level (P603), that could cause F0021.

Changes in the new application version

- 1) Modified Low Voltage Level Protection Level with a safety margin value, avoiding F0021.



NOTE!

This application is not available in the WLP software.