


CPCS-X AND PCSX-01 KITS - CFW11/CFW70X ABC

KITS CPCS-X Y PCSX-01 - CFW11/CFW70X ABC

KITS CPCS-X E PCSX-01 - CFW11/CFW70X ABC



Clamp
Abrazadera
Abraçadeira



*

Screw M3 x 8
Tornillo M3 x 8
Parafuso M3 x 8



Clamp
Abrazadera
Abraçadeira



Screw M4
Tornillo M4
Parafuso M4



*

Screw M4 / M5
Tornillo M4 / M5
Parafuso M4 / M5



*

Spacer M3 x 5.8
Separador M3 x 5.8
Espaceador M3 x 5.8

Control Cables⁽¹⁾
Cables de Control⁽¹⁾
Cabos de Controle⁽¹⁾

Power Cables
Cables de Potencia
Cabos de Potência



Remote HMI
HMI Remoto
HMI Remota

* Torque { M3: 0.5 N.m (4.4 lbf.in)
M4: 1.7 N.m (15.0 lbf.in)
M5: 2.5 N.m (22.1 lbf.in)

(1) Not included in PCSx-01 kit.
(1) No incluido en el kit PCSx-01.
(1) Não incluso no kit PCSx-01.

