

417100995-KFIX-CFW08-M2

Kit Description:

417100995 - KFIX-CFW08-M2
CFW 08 FIXATION KIT
Only models: 7.3,10,16 A/200-240V
2.7,4.3,6.5,10A/380-480V

Kit Content

| Qtde | Description | Item |
|------|---------------------------|-----------|
| 1 | Inferior metallic support | 6432.2025 |
| 4 | Screw M4 x 12 | 0701.0044 |
| 1 | Superior metallic support | 6432.2026 |

1-Fix the inferior metallic support with screws;
2-Lean on the inverter in the inferior support and then
3 - Fix the superior support with the screws.
Fixation mode:

Descripción del Kit:

417100995 - KFIX-CFW08-M2
KIT DE FIJACIÓN DEL CFW 08
Solamente modelos: 7.3,10,16 A/200-240V
2.7,4.3,6.5,10A/380-480V

Contenido del Kit

| Qtde | Descrição | Item |
|------|---------------------------|-----------|
| 1 | Soporte metálico inferior | 6432.2025 |
| 4 | Tornillo M4 x 12 | 0701.0044 |
| 1 | Soporte metálico superior | 6432.2026 |

1- Fijar el soporte inferior con tornillos;
2- Apoyar el convertidor en el soporte inferior y
3- Fijar, con los tornillos, el soporte superior.
Modo de fijación


Descrição do Kit:

417100995 - KFIX-CFW08-M2
KIT DE FIXAÇÃO DO CFW 08
Somente modelos: 7.3,10,16 A/200-240V
2.7,4.3,6.5,10A/380-480V

Conteúdo do Kit

| Qtde | Descrição | Item |
|------|---------------------------|-----------|
| 1 | Suporte metálico inferior | 6432.2025 |
| 4 | Parafuso M4 x 12 | 0701.0044 |
| 1 | Suporte metálico superior | 6432.2026 |

1 - Fixar o suporte inferior com parafusos;
2 - Apoiar inversor no suporte inferior e
3 - Prender, com os parafusos, o suporte superior.
Modo de fixação:



1 - Superior support / Soporte superior / Suporte superior
2 - Inferior support / Soporte inferior / Suporte inferior