

417100994-KFIX-CFW08-M1

Kit Description:

417100994 - KFIX-CFW08-M1
CFW 08 FIXATION KIT
Only models: 1.6,2.6,4.0A/200-240V
1.0,1.6,2.6,4.0A/380-480V

Kit Content

Qtde	Description	Item
1	Inferior metallic support	6432.2022
4	Screw M4 x 12	0701.0044
1	Superior metallic support	6432.2023

1-Fix the inferior metallic support with screws;
2-Lean on the inverter in the inferior support and then
3 - Fix the superior support with the screws.
Fixation mode:

Descripción del Kit:

417100994 - KFIX-CFW08-M1
KIT DE FIJACIÓN DEL CFW 08
Solamente modelos:1.6,2.6,4.0A/200-240V
1.0,1.6,2.6,4.0A/380-480V

Contenido del Kit

Qtde	Descrição	Item
1	Soporte metálico inferior	6432.2022
4	Tornillo M4 x 12	0701.0044
1	Soporte metálico superior	6432.2023

1- Fijar el soporte inferior con tornillos;
2- Apoyar el convertidor en el soporte inferior y
3 - Fijar, con los tornillos, el soporte superior.

Modo de fijación:


Descripción del Kit:

417100994 - KFIX-CFW08-M1
KIT DE FIXAÇÃO DO CFW 08
Somente modelos:1.6,2.6,4.0A/200-240V
1.0,1.6,2.6,4.0A/380-480V

Conteúdo do Kit

Qtde	Descrição	Item
1	Suporte metálico inferior	6432.2022
4	Parafuso M4 x 12	0701.0044
1	Suporte metálico superior	6432.2023

1 - Fixar o suporte inferior com parafusos;
2 - Apoiar inversor no suporte inferior e
3 - Prender, com os parafusos, o suporte superior.
Modo de fixação:



1 - Superior support / Soporte superior / Suporte superior
2 - Inferior support / Soporte inferior / Suporte inferior