

CCS RACK – CFW-11/CFW70X



Clamp
Abrazadera
Abraçadeira



* Screw M3 x 8
Tornillo M3 x 8
Parafuso M3 x 8

Control Cables
Cables de Control
Cabos de Controle



* Spacer M3 x 5.8
Separador M3 x 5.8
Espaçador M3 x 5.8

Remote HMI
HMI Remoto
HMI Remota

* Torque M3: 0.5 N.m (4.4 lbf.in)