



Solar Pump Drive V2.01 Application Information

Equipment: CFW700

Firmware Version: V2.30 or higher

WLP Software Version: -

New Application Version: 2.01

Old Application Version: 2.00

Document Number (Application Manual): 10006763201 / 02

Functional deviations in the old application version

- 1) Stopping the drive below Minimum Voltage Tracking SP (P1022)

Changes in the new application version

- 1) Modified Low Level detection on Running (DC Check OK) from Minimum Voltage (P1022) to Undervoltage Level



NOTE!

This application is not available in the WLP software.