



Dancer Center Winder Application Information

Equipment: CFW-11

Firmware Version: V2.05 or higher

WLP Software Version: V9.10 or higher

New Application Version: CWDA-1_22.apl

Old Application Version: CWDA-1_21.apl

Document Number: 10001147511 / 00

Functional deviations in the old application version

- 1) In the monitoring dialog of the analog input parameters, the value shown in P0021 (AI4) was wrong.

Changes in the new application version

- 1) Created the F799 fault to indicate that the CFW-11 software version (P0023) is not compatible with the software version used in developing of this application. For the Dancer Center Winder application is necessary that the software version is greater than or equal to 2.05.
- 2) Created the F797 fault to indicate that the control type (P0202) is not compatible with the type necessary for this application. For the Dancer Center Winder application is necessary to use vector control with encoder.



NOTE!

Appendix 1 shows how to import Dancer Center Winder application to WLP.

Appendix 1 – How to Import Application to WLP

- 1) In the WLP Ladder Programmer, in “Tools” menu, select the “Import Application to WLP” option;
- 2) Search “CWDA-1_22.apl” archive and press “OK”;
- 3) The Dancer Center Winder will be imported to WLP;
- 4) To select the application, in “Tools” menu, “Application” option, “CFW11”, “Create”, “Center Winder”, select “Dancer” option.